Sensor Type Hand Helds

Date 3/8/2002

Source Mfg/Test

Problem **Part Nr.** GT-521

OK

GT-521 with fully charged battery and the battery charger connected, the unit will come on, but after pushing start the unit locks up.

Product AIR Products

Solution

The lithium back up battery (390068) is high resistance, dead. This causes the 3.6 volt line to float up to 5 volts locking up the unit. Replace the battery and reprogram the unit.

This must be done at the factory.