BT-637 BENCH TOP PARTICLE MONITOR

SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

REPAIR AND FIELD MAINTENANCE

This instrument must be returned to the factory for Calibration. The turn around time is generally less than five (5) working days.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

BASIC SERVICE(S)

ORDER #	DESCRIPTION
SVC0108	CALIBRATION, BT-637 PARTICLE MONITOR Includes Calibration and NIST Traceable Certificate Inspect Filter, Inspect, Clean Optical Sensor, Pump and Tubing. Cycle and Test Battery; Install any applicable upgrades. *Includes "As Received" and "As Left" NIST Cal certificates*
SVC3002	CALIBRATE G3120 TEMP/RH SENSOR
SVC0109	ISO 21501-4 CALIBRATION

Parts Marked with an Asterisk (*) ahead of the part number will be replaced as needed during the calibration

REPLACEABLE PARTS

	PART #	DESCRIPTION
	550065	RS232 CABLE, BT-637
	500784	USB CABLE, BT-637
	80643	BATTERY CHARGER, BT-637
	G3111	ZERO FILTER
*	80340	IN-LINE FILTER
	G3110	ISO-KINETIC SAMPLING PROBE
*	80642	BATTERY PACK, BT-637
*	8650	PUMP ASSY
	G3115	PRINTER FOR USE WITH HANDHELD MONITORS
	750509	PRINTER PAPER
	G3120	TEMPERATURE / HUMIDITY SENSOR
	9801	FLOW METER
	BT-637-9800	USER MANUAL, BT-637 PARTICLE MONITOR

BT-637

MOI P/N: BT-637

USB Cable

MOI P/N: 500784

Serial Cable

MOI P/N: 550065

Iso-Kinetic Inlet

MOI P/N: G3110

Battery Charger

MOI P/N: 80643

Zero Particulate Filter



MOI P/N: G3111

BT-637 Optional Equipment

Printer

MOI P/N: G3115

Dwyer™ Ball Flow Meter

MOI P/N: 9801

Temperature & Humidity Probe

MOI P/N: G3120