AEROCET 531S

SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

---

REPAIR AND FIELD MAINTENANCE

This instrument must be returned to the factory for Calibration. The turn around time is generally less than five (5) working days.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

BASIC SERVICE(S)

ORDER #	DESCRIPTION
SVC0104	CALIBRATION, AEROCET 531, 531S PARTICULATE PROFILER Includes Calibration and NIST Traceable Certificate Inspect Filter, Inspect, Clean Optical Sensor, Pump and Tubing. Cycle and Test Battery; Install any applicable upgrades. *Includes "As Received" data and "As Left" data certificates*
SVC3002	BENCH CAL, G3120 TEMP/RH SENSOR, NIST

Parts Marked with an Asterisk (*) ahead of the part number will be replaced as needed during the calibration

REPLACEABLE PARTS

	PART #	DESCRIPTION
	3228	RS232 SERIAL CABLE
	400113	POWER CORD, GT-526S, AEROCET 531S
	500787	USB CABLE, MALE A TO MINI MALE B
	G3110	ISO-KINETIC SAMPLING PROBE
	8517	CARRYING CASE
	390031	BATTERY CHARGER, 8.4 VDC,1.5A,LITHIUM ION,SMART
	80248	COMET TERMINAL SOFTWARE CD
	9801	FLOW METER
	G3111	ZERO FILTER
	G3120	TEMPERATURE / HUMIDITY SENSOR
	G3115	PRINTER FOR USE WITH HANDHELD MONITORS
	750509	PRINTER PAPER
*	80458	BATTERY PACK, 7.4 VDC, 2000 mAh
*	8650-2	PUMP ASSY., FURGUT
*	8538	IN-LINE FILTER ASSEMBLY

AEROCET 531S Standard Equipment

AEROCET 531S
P/N AEROCET 531S

Manual
AEROCET 531S-9800

Comet Software CD
P/N 80248

Calibration Certificate
AEROCET 531S-9600

Battery Charger
P/N 390031

Power Cord
P/N **400113**

ISO-Kinetic Probe
P/N G3110

Zero Count Filter
P/N G3111

Carrying Case
P/N 8517

USB Cable
P/N 500787

Custom Serial Cable
P/N 3228

Printer

MOI P/N: G3115

Optional Equipment

Dwyer™ Ball Flow Meter

MOI P/N: 9801

Temperature & Humidity Probe

MOI P/N: G3120