

Sensor Type Hand Helds

Date

Source In-House

7/8/2003

Problem **Part Nr.** GT-321

OK

GT-321 runs continuously after starting sample.

Product AIR Products

Solution

Battery may be overcharged or overcharging, causing voltage to float in excess of 4V.

This may cause any of several problems, including continuous running. The Particle counter and charger should be sent to the factory for testing.

Call the factory at 541-471-7111 and ask for the Service Department to get a Return Authorization for this repair.

