

Sensor Type Hand Helds

Source In-House

Date

6/12/2001

Problem **Part Nr.** GT-321, KM-09

OK X

Unit fails zero count test. Pump is making noise.

Product AIR Products

Solution

Replace pump. Faulty pump is also causing noise spiking on processor and giving counts when there are actually no particles in chamber.

