

GT-521S PARTICLE COUNTER

SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

REPAIR AND FIELD MAINTENANCE

This instrument must be returned to the factory for Calibration. The turn around time is generally less than five (5) working days.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

BASIC SERVICE(S)

ORDER #	DESCRIPTION
SVC0103	CALIBRATION, GT-521, GT-521S HAND HELD Includes Calibration and NIST Traceable Certificate Inspect Filter, Inspect, Clean Optical Sensor, Pump and Tubing. Cycle and Test Battery; Install any applicable upgrades. <i>Includes "As Received" data and "As Left" data certificates</i>
SVC3002	BENCH CAL, G3120 TEMP/RH SENSOR, NIST
SVC0109	ISO 21501-4 CALIBRATION

REPLACEABLE PARTS

PART #	DESCRIPTION
3228	RS232 SERIAL CABLE
400113	POWER CORD, GT-526S, AEROCET 531S
500787	USB CABLE, MALE A TO MINI MALE B
G3110	ISO-KINETIC SAMPLING PROBE
8517	CARRYING CASE
390031	BATTERY CHARGER, 8.4 VDC, 1.5A, LITHIUM ION, SMART
80248	COMET TERMINAL SOFTWARE CD
9801	FLOW METER
G3111	ZERO FILTER
G3120	TEMPERATURE / HUMIDITY SENSOR
G3115	PRINTER FOR USE WITH HANDHELD MONITORS
750509	PRINTER PAPER
* 80458-1	BATTERY PACK, 7.4 VDC 2000 mAh
* 8650-2	PUMP ASSY., FURGUT
580336	INLINE FILTER, (Between Sensor and Pump)
* 8538	IN-LINE FILTER ASSEMBLY

Note: Parts marked with an asterisk (*) will be replaced as needed during calibration.