# **AEROCET 531**

## SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526 Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

**REPAIR AND FIELD MAINTENANCE** This instrument must be returned to the factory for Calibration. The turn around time is generally less than five (5) working days.

#### **RETURN AUTHORIZATION**

Prior to any product return, please contact the factory for a return authorization number.

#### **BASIC SERVICE(S)**

ORDER #	DESCRIPTION
SVC0104	CALIBRATION, AEROCET 531 PARTICULATE PROFILER
	Includes Calibration and NIST Traceable Certificate
	Inspect Filter, Inspect, Clean Optical Sensor, Pump and Tubing.
	Cycle and Test Battery; Install any applicable upgrades.
	Includes "As Received" data and "As Left" data certificates
SVC3002	CALIBRATE G3120 TEMP/RH SENSOR

Parts Marked with an Asterisk (\*) ahead of the part number will be replaced as needed during the calibration

### **REPLACEABLE PARTS**

PART #	DESCRIPTION
3228	RS232 SERIAL CABLE
400100	CABLE, AC POWER
510640	POWER SUPPLY
G3110	ISO-KINETIC SAMPLING PROBE
8517	CARRYING CASE
993020	MINIATURE SCREW DRIVER
3289	AEROCOMM SOFTWARE
AEROCOM-9800	AEROCOMM SOFTWARE MANUAL
G3111	ZERO FILTER
G3120	TEMPERATURE / HUMIDITY SENSOR
G3115	PRINTER FOR USE WITH HANDHELD MONITORS
750509	PRINTER PAPER
9285	Battery Pack, GT-521, Aerocet 531, GT-526
8650	PUMP ASSY
8538	IN-LINE FILTER ASSEMBLY