

076B RADIATION SHIELD

SERVICE MAINTENANCE, REPAIR, SPARE PARTS

Met One Instruments, Inc.; 1600 NW Washington Blvd.; Grants Pass, OR. 97526
Ph. 541-471-7111; Fax 541-471-7116; E-mail: service@metone.com

REPAIR AND FIELD MAINTENANCE

A complete repair and service department is maintained at our factory in Grants Pass, Oregon, and at our regional service facility in Dallas, Texas. Most repairs can be made in the field by a simple substitution of components. Some repairs do require recalibration following the replacement of faulty components. If calibration standards are not available, the instrument can be returned to our service facility. The turn around time is generally less than five (5) working days.

RETURN AUTHORIZATION

Prior to any product return, please contact the factory for a return authorization number.

BASIC SERVICE(S)

ORDER #	DESCRIPTION
SVC0053	076/060/083 RH TEMP MOTOR SHIELD STD. REPAIR Includes labor to check and Cal 083D/E RH Sensor (3 Point), and check Cal on 060 Temperature Sensor (2 point) if installed.

REPLACEABLE PARTS

PART #	DESCRIPTION
2273	FAN MOTOR 115VAC MODIFIED
2274	FAN MOTOR 220VAC MODIFIED
2275	FAN MOTOR 12VDC MODIFIED
390807	HOLE PLUG 1/4"
510508	SENSOR CLIP, 3/8 DIA, 076B
510509	SENSOR CLIP, 3/4 DIA, 076B
670202	LATCH, FUW 076B

****CONSULT FACTORY FOR CABLE PRICING**